

**DEFECT LIST OF BN-1524 BUS**  
**MODEL NO-**

Ser.	Description	Deno	Qty
1.	Radiator water leaky suspect radiator tube perforated. Radiator to be renewed.	No	01
2.	Brake booster defective. Suspect brake booster repair kit & Clutch booster repair kit renewed.	No	02
3.	Brake air distributor unit defective, Brake air distributor unit kit to be renewed.	Set	01

  
M ABDUL KADER  
Lt BN  
Motor Transport Officer